

Site Assessment

Assessor	J Baxter / L Finch				
Date	25.11.2025				
Assessment Type	Review				
Suburb	Bayswater				
Street/ Near Street	King William Street near Hill Street				
COR File	00373 94 F5				
School/s	Bayswater Primary School St Columba's Primary School				
School Zone	No		Crossing Zone	No	
Speed Limit	40 Km/H (Permanent)		Method of Operation	Single	
Number of Lanes	Vehicles	2	Other Lanes	Turning	No
	Bus/Bike	0		Passing	No
Road Width	10.8 M		Cut out	Yes Width 2.4 M	
Median/ Refuge/ Traffic Island	Yes Width 1.3 M		Flashing Lights	On approach - Yes	
Painted Lines	Yes	Median	Bends	Is line of sight affected? N/A	
Bends	N/A		Crest/ Incline	Is line of sight affected? No	
Crest/ Incline/ Decline	Southeast Of Crossing		Round About	Is line of sight affected? No	
Round About	Southeast Of Crossing		Symbolic sign distance	Southeast 85.2 M	
Symbolic sign distance	Northwest 115 M		Tactiles used	Pram Ramps	No
Tactiles used	Centre of road	No		Tactiles Condition	N/A

Sight Distance	Northwest 80-120 M	Sight Distance	Southeast 80-120 M
Bus Stops	Between 0-50 metres on approach of the crossing	Bus Stops	Between 0-50 metres on departure of the crossing
	No		Yes (40m southeast)
Other Environmental Factors (i.e vegetation, power poles and parking restrictions)	<ul style="list-style-type: none"> • Parking restrictions on approaches (signs/road markings) - Yes • Trip Hazards - No • Distance from stop line to ped line school side 6.7 M • Distance from stop line to ped line non-school side 6.8 M • Stop lines through Cycle and Bus lanes - No • Painted lines condition - Worn • Ped lines - Yes 		
Hazards Observed	<ul style="list-style-type: none"> • Compliance of parking restrictions YES/NO/N/A? • Bus/Vehicle parking within 20 M on approach or 10 M on departure of crossing YES on both sides during crossing operation 		
Photo's (10 as per arrows)			

* Note – site assessment must be completed while crossing is operational